

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
MASS,
11-DED,
1-

Addendum to
Jonathan Fairbanks House
511 East Street
Dedham
Norfolk County
Massachusetts

HABS No. MA-223

Photos MA-223-1 and -2 were transmitted to the Library of Congress.

Stanley Mixon, Photographer May 1940

- MA-223-~~3~~⁸ VIEW FROM WEST END
MA-223-~~4~~⁹ GENERAL VIEW FROM SOUTHEAST
MA-223-~~5~~¹⁰ GENERAL VIEW FROM WEST END OF EAST ELEVATION
MA-223-~~6~~¹¹ VIEW OF WEST END OF EAST ELEVATION
MA-223-~~7~~¹² DETAIL OF TYPICAL WINDOW, EAST ELEVATION
MA-223-~~8~~¹³ INTERIOR, EAST ELEVATION, BEDROOM, FIRST FLOOR
MA-223-~~9~~¹⁴ INTERIOR, EAST ELEVATION, PARLOR, FIRST FLOOR
MA-223-~~10~~¹⁵ INTERIOR, WEST ELEVATION, PARLOR, FIRST FLOOR
MA-223-~~11~~¹⁶ INTERIOR, WEST WALL OF KITCHEN, FIRST FLOOR,
MAIN HOUSE
MA-223-~~12~~¹⁷ INTERIOR, EAST WALL OF KITCHEN, FIRST FLOOR,
MAIN HOUSE
MA-223-~~13~~¹⁸ INTERIOR, DETAIL OF FIREPLACE, EAST ROOM,
FIRST FLOOR, MAIN HOUSE
MA-223-~~14~~¹⁹ VIEW OF HALLWAY, FIRST FLOOR, MAIN HOUSE
MA-223-~~15~~²⁰ DETAIL OF CLOSET BOARDING, BEDROOM, SECOND FLOOR
MA-223-~~16~~²¹ INTERIOR, BEDROOM, SECOND FLOOR
MA-223-~~17~~²² DETAIL OF DOOR TO BEDROOM, SECOND FLOOR
MA-223-~~18~~²³ INTERIOR, BEDROOM WITH FIREPLACE AND DOOR DETAIL,
SECOND FLOOR

- MA-223-~~19~~²⁴ DETAIL OF DOOR, SECOND FLOOR
- MA-223-~~20~~²⁵ INTERIOR, VIEW OF FIREPLACE AND DOOR,
SECOND FLOOR
- MA-223-~~21~~²⁶ INTERIOR, VIEW LOOKING WEST IN HALLWAY,
SECOND FLOOR
- MA-223-~~22~~²⁷ DETAIL OF BEAM ENDS AND JOISTS, WEST ROOM
NORTH ELEVATION, SECOND FLOOR
- MA-223-~~23~~²⁸ INTERIOR, BEDROOM WITH WOOD CLOSET,
SECOND FLOOR
- MA-223-~~24~~²⁹ INTERIOR, WORKROOM, SECOND FLOOR, MAIN HOUSE
- MA-223-~~25~~³⁰ DETAIL OF CLOSET DOOR, BEDROOM, SECOND FLOOR